

http://www.luxierusa.com/

Installation Guide

Contemporary Shower Trim Single Handle Shower Only Trim Model Number: CL206-TB CL206-TC







Tools you will need:



Adjustable Wrench



Pipe Tape

Groove join pliers

SAFETY TIPS:


• If you use soldering for the installation of the faucet, the seats, cartridges and washers will have to be removed before using flame. Otherwise, warranty will be void on those parts.

• Cover your drain to avoid losing parts.

• 32°F-131°F

luxier

Model Number: CL206-TB CL206-TC



Trouble-Shooting


If you've followed the instructions carefully and your faucet still does not work properly, take these corrective steps.

Problem -Leaks underneath Shower Head.	<u>Cause</u> -Retainer Shower Head has come loose. O-ring is dirty or damaged.	<u>Action</u> -Tighten the retainer nut. Clean or replace O-ring.
--	---	---



Model Number: CL206-TB CL206-TC

Replacement Parts



Limited Lifetime Warranty

Luxier USA warrants to the original purchaser that its products will be free from defects in workmanship and materials. This warranty does not cover any other labor or service charges associated with the removal, repair, or reinstallation of Luxier products. This express warranty does not apply to products that have been damaged as a result of misuse, abuse, negligence, accident, faulty installation or maintenance practices and/or used in any manner contrary to those recommended by the manufacturer.